

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Biloxi Decon Area	Facility Location ID:	BX01
Assessment Date :	7/17/2010	Incident Name :	BP Spill
Physical Location :	164 8th Street		
City, State :	Biloxi, MS	County :	Harrison

ASSESSMENT INFORMATION

General Site Information and Observations			
1. All waste stored in lined rolloff boxes?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
5. How many samples were collected?			
Additional Comments : 3ea. 55 gallon drums containing oily PPE were properly covered. An empty roll-top container for oily waste was staged inside the decon area, lined and covered. No visible oil seen in the oil water separator. No concerns regarding waste management practices were noted during the visit.			